



The Firmware of the Valve-Protector Sequent Modules (40127-S4/S6) has a new Firmware **version 1.5.7**

Please note!

The change means that the modules builds pressure up only when also be an additive shock occur (see yellow line). In the previous firmware version was always a pressure of about 2 bar that mined at an additive shock and rebuilt immediately. As seen in the picture now the pressure build-up (yellow line) started only when the blue line (pump activity) reaches 100%. The pressure reduction of the yellow line shows the ejection of the additive.